Despite Grant 1988 - 64 (1986 - 54) the Jonate of Parks of the Section 1985 - 1		and the state of t
EF 4470		
1. MALFUNCT	ION REPORTED	SENT Ø8/1548Z.
2. FYI SINGLE SPEED	SHUTTER WAS USED	ON
OR MSN 3229. THERE WAS	NO REQUIREMENT TO	O USE TWO SPEED SHUTTER
N THIS SORTIE SINCE MSN	REQUIREMENTS SPE	CIFIED FAST SHUTTER SPEED
ND F-10 APERTURE. THE	NORMAL SHUTTER ANI	D FAST POSITION OF TO
PEED SHUTTER ARE IDENTION	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
3. THERE IS NO REASON	v why	CANNOT BE USED ON
EXT SORTIE WITH SO-130 F	TILM HOWEVER WE SI	EE NO ADVANTAGE IN
SING TWO SPEED SHUTTER.		
4. RECOMMEND USE OF S	SN 118,	WITH SO-130 FILM
SING 1/150 TOT AND F-10	APERIURE AND NORM	MAL SHUTTER.
OPSECRET		
O P S E C R E T	08715	AR7 FYI 3 CN 10 3000
O P S E C R E T N Ø149 X 4470 REQUIREMENT F-10 NO RE		48Z FYI 3 SN 12 3229

T O P S E C R E T 081932Z 25X1 - IMMEDIATE CITE 25X1 25X1 4471 25X1 FYI ESTIMATE FOOTAGE OF 25X1 THE 80 FT REPORTED IN SHUTTER OPERATING WAS LESS THAN 100 FT. 25X1 THE OF WHICH NEGLIBLE AMOUNT EXPOSED IN 25X1 TGT AREA. TRANSPORT DID NOT PLAY A PART IN THE CONFIG MALFUNCTION. PLS ADVISE IF YOU DESIRE IMMEDIATE SHIPMENT RETAINEDS OF 3229 TAKE WITH ROUTE OVERLEDS IAW REF. C-130 WILL BE RETABLE 25X1 PHFING YOUR REPLY. TOPSECRET 25X1 CFN 0148 X 4471 FYT CONFIG 3229 C-130 BT

Sanitized Copy Approved for Release 2009/10/29: CIA-RDP89B00569R000700110007-9